

JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

December 19, 2006

FILE COPY

Katie Hackney, Administrator Country Time Assisted Living Center, LLC 277 S Main St Star, ID 83669

License #: RC-775

Dear Ms. Hackney:

On November 17, 2006, a life safety code survey was conducted at Country Time Assisted Living Center, LLC. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Chris Laumann, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

CHRIS LAUMANN

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

CL/slc

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



JAMES E. RISCH – Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T – Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

November 21, 2006

Katie Hackney, Administrator Country Time Assisted Living Center, LLC 277 S Main St Star, ID 83669 FILE COPY

Dear Ms. Hackney:

On November 17, 2006, a life safety code survey was conducted at Country Time Assisted Living Center, LLC. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by December 17, 2006.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely.

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

PRINTED: 11/20/2006 FORM APPROVED **Bureau of Facility Standards** (X3) DATE SURVEY STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: (X2) MULTIPLE CONSTRUCTION COMPLETED AND PLAN OF CORRECTION 01 - ENTIRE BUILDING A. BUILDING B. WING 13R775 11/17/2006 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 277 S MAIN ST **COUNTRY TIME ASSISTED LIVING CENTER, L** STAR, ID 83669 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES (X5)(X4) ID (EACH DEFICIENCY MUST BE PRECEDED BY FULL (EACH CORRECTIVE ACTION SHOULD BE COMPLETE **PREFIX** PRÉFIX REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE DATE TAG TAG DEFICIENCY) R 000 Initial Comments R 000 The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on November 17, 2006. The surveyor conducting the survey was: Chris Laumann Health Facility Surveyor Facility Fire safety & Construction

Bureau of Facility Standards

TITLE

(X6) DATE



BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888 ASSISTED LIVING Non-Core Issues Punch List

Facility Name	Physical Address	Phone Number
Country Time Assisted Living	277 S. Man St.	608) 863-0688
Administrator J	City '	ŽIP Code
latie Baker	Star, Idho	83669
Survey Team Leader	Survey Type	Survey Date
Chris Lauman	Fire/Life Safety	11/17/06
		

	1010 CO	human tire/Lite Satety 11/1/0	26	
	CORE ISSU		,	
ITEM #	RULE # 16.03.22	DESCRIPTION	DATE RESOLVED	BFS USE
1,	16,0320.404	NFPA 101 (1988 edition) regulament: Hazardous crea seperat	v n	
		of laundy room. The laundy room did not have a self		
		closing door. The mechanical roun/ storage wan did not		
		maintain a small resistive seperation from the 1957 of the		
		facility Two Ift by 1'6 ft grates were installed in the		
	. :	wall and penetrating to the capillos. The mechanical room/		20 9 17 35
		Storage room is required to have an auto closer as well.		0.00
2	405,01,B	Multidua adapters were found in Rm I jouvering a lamp and		8 8 8
*******************************		a Clock Anomer was found in Rm. 4, and Rm 11 Extension		ansva
		cords were found in Rm. 10 and Rm 13		6. S. N. N. S.
3.	405.05	The hand rails in the "left hallway" were all loose allong		
		the entire length of the hallway.		0.000
4.	415, 02.	No professional respection documentation of fuel Fre bruty obvices		
	u/v ∖	could le produced.		809 G
	415,04	no inspection of the Fire Alarm System could be produced		90418
	415.06	no the water policy round be produced.		
Respon	se Required Date	Signature of Facility Representative	Date Signed	
12/1	7/06	1 x) Y Y AUCH COLL Y \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		

BFS-686 March 2006